



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed PRB

Report Date: **07/15/2014**

Mine Name: Torrey Quarry	Permit Number: M/055/0016	Mine Status: Active
Operator Name: Star Stone Quarries	Inspection Date: 07/10/2014	Permit Fees: Paid
Inspector(s): Wayne Western	Inspection Time: 10:40 - 11:00	Bond Amount: \$40,000
Attendee(s): John Reay	Weather: Warm and fair	Bond Escalation: 08/24/2016
Inspection Purpose: Routine inspection		Prior Inspection: 05/22/2013

Conclusions and Recommendations

The site is stable. The Division should continue to monitor the site.

Elements of Inspection		Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds Permit fee and bond are current.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2.	Public Safety (shafts, adits, trash, signs, highwalls) No highwalls, adits, or shafts on site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3.	Protection of Drainages/Erosion Control No signs of erosion.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.	Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>
5.	Roads (maintenance, surfacing, dust control, safety) Roads are in good condition.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6.	Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8.	Soils	<input type="checkbox"/>	<input type="checkbox"/>
9.	Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10.	Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: _____

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M055-Wayne/M0550016-Torrey_Quarry/inspections/Insp07102014.pdf

